




Site: 005 Homestead Structural Artifacts  
(PN99-0424-1-6)



Site: 005 Gravel Pit  
(PN99-0424-1-7)





Site: 005 Gravel Pit/Mound  
(PN99-0424-1-8)

## **Attachment B**

### **Supporting Information for Site #005**

## NEW SITE IDENTIFICATION

### Part A – To Be Completed By Observer

1. Person Initiating Report: Jacob Harris

Phone: 526-1877

Contractor WAG Manager: Douglas Burns

Phone: 526-4324

2. Site Title: 005, Excavation Pit/Mound and Debris East of Guard Gate 3

3. Describe the conditions that indicate a possible inactive or unreported waste site. Include location and description of suspicious condition, amount or extent of condition and date observed. A location map and/or diagram identifying the site against controlled survey points or global positioning system descriptors shall be included to help with the site visit. Include any known common names or location descriptors for the waste site.

There is a large excavation pit/mound, debris and 2 small pits about 200 yards east of Guard Gate 3. During the July 1999 site visit, the observed surface debris included glass, metal, wire, wood, and rusted cans. There are 2 small pits that appear to be associated with the debris. One pit contains concrete and old pieces of wood and the other contains wood. The large gravel pit/mound appears to be from a separate excavation activity. The GPS coordinates for this site are  
The reference number for this site is 005 and can be found on the summary map provided.

### Part B – To Be Completed By Contractor WAG Manager

4. Recommendation:

☒ This site meets the requirements for an inactive waste site, requires investigation, and should be included in the INEEL FFA/CO Action Plan. Proposed Operable Unit assignment is recommended to be included in the FFA/CO.  
WAG: \_\_\_\_\_ Operable Unit: \_\_\_\_\_

☐ This site DOES NOT meet the requirements for an inactive waste site, DOES NOT require investigation and SHOULD NOT be included in the INEEL FFA/CO Action Plan.

5. Basis for the recommendation:

The conditions that exist at this site indicate the potential for an inactive waste site according to Section 2 of MCP-3448 Reporting or Disturbance of Suspected Inactive Waste Sites.

The basis for recommendation must include: (1) source description; (2) exposure pathways; (3) potential contaminants of concern; and (4) descriptions of interfaces with other programs, as applicable (e.g., D&D, Facility Operations, etc.)

6. Contractor WAG Manager Certification: I have examined the proposed site and the information submitted in this document and believe the information to be true, accurate, and complete. My recommendation is indicated in Section 4 above.

Name: \_\_\_\_\_ Signature: \_\_\_\_\_ Date: \_\_\_\_\_



## PROJECT DOCUMENT REVIEW RECORD

**DOCUMENT TITLE/DESCRIPTION:**

Site 005 Track 1 Decision Documentation Package, OU 10-08: Excavation Pit/Mound and Debris East of Guard Gate 3 (DOE/ID 10934)

DATE: <u>March 29, 2002</u>		REVIEWER: <u>IDEO</u>		
ITEM NUMBER	SECTION NUMBER	PAGE NUMBER	COMMENT	RESOLUTION
<b>COMMENTS</b>				
1		8	The second paragraph states "The volume of pit/hole is consistent." Please clarify what the volume of the pit/hole is consistent with. The reader may assume it is consistent with the volume of the mound but it is not clear. Please clarify.	Comment incorporated. However, because a previous sentence in the paragraph already stated, "The pit and mound are very similar in size....," we have deleted the unclear sentence: "The volume of pit/hole is consistent."
2		9	The second paragraph of Block 1 states "The gravel was likely used for present-day INEEL road construction activities." If material was removed then the volumes of the pit and mound should not be consistent as inferred on page 8. Please clarify.	Comment incorporated. We have deleted the sentence.
3		Attachment B. New Site Identification Form	Last page - Part 3 states the site number 016 but the rest of the description is for site 005. This was probably a collating error when assembling the packets.	Comment incorporated. We have changed the "016" to "005."